

Listed on State Register

VT ACHP Date: 5.7.80

STATE OF VERMONT
Division of Historic Sites
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1105-25

NEGATIVE FILE NUMBER:

76-A-90

UTM REFERENCES

18	665730	4825530
Zone	Easting	Northing

U.S.G.S. QUAD. MAP:
Rutland Quad., 7.5' Series

COUNTY: Rutland
TOWN: Clarendon (No. Clarendon)
LOCATION:
FUNCTIONAL TYPE: Commercial
COMMON NAME: No. Clarendon Texaco
OWNER: Sumner Page, Hazel Stork,
ADDRESS: Katherine Horvath
No. Clarendon, Vermont
ACCESSIBILITY TO PUBLIC:
Yes No Restricted
LEVEL OF SIGNIFICANCE:
Local State National
DATE BUILT: ca. 1925

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: Vacant

ORIGINAL USE: Gas Station

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good to
Fair Deteriorated

THEME:

STYLE: Neo-Colonial

GENERAL DESCRIPTION:

Structural System

1. Foundation: Brick Stone Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Balloon Western Platform Post & Beam
 - b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
 - c. Iron
 - d. Steel
 - e. Other:
3. Wall Covering: Clapboard Wood Shingle Board & Batten
Shiplap Novelty Stucco Tile Brick Stone
Slate Sheet Metal Asphalt Shingle Aluminum
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Vault: Brick Stone Concrete
 - c. Other:
5. Roof Covering: Wood Shingle Asphalt Shingle Tile
Slate Sheet Metal Paper Built Up Rolled
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Dormers Bay Windows Ells
Chimneys Cupolas Wings Sheds Other: Balustrade

Number of Stories: 1

Approximate Dimensions: 12' x 12'

Roof Style: Gable Gambrel Flat Shed Hip Mansard
Jerkinhead Monitor Saw Tooth Other:
With Belcast With Parapet With False Front

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Other: Demolition

LOCAL ATTITUDES:

Positive Negative Mixed
Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Three bays wide, two bays deep. Front service canopy with hip roof, wood posts, balustrade and urn finials. Narrow attached shed with rolled asphalt roof at south wall.

RELATED STRUCTURES:


None

STATEMENT OF SIGNIFICANCE:

In the 1920's and 30's, when travel by automobile became common, North Clarendon was developed as a tourist service area. This gas station is one of the few remaining structures in the village associated with this early roadside development along old Route 7. The building's small size reflects its initial use as a filling station, rather than auto repair and service center, a concept in gas station design that did not become widespread until the World War II era.

UNIVERSITY OF VERMONT

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Other:

RECORDED BY:

Kathlyn Hatch

ORGANIZATION:

VT Division for Historic Preservation

DATE RECORDED:

5-76



1105-25

VERMONT DIVISION FOR HISTORIC PRESERVATION

CO. RUTLAND TOWN No. CLARENDON DATE 6/76
SUBJECT GAS STATION VIEW E
FILE # 76-A-90 CREDIT KATHLYN HATCH