

Listed on State Register

VT ACHP

Date:

5-17-80

STATE OF VERMONT
Division of Historic Sites
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1105-19

NEGATIVE FILE NUMBER:

UTM REFERENCES

18	664040	4823770
Zone	Easting	Northing

U.S.G.S. QUAD. MAP:

Rutland Quad., 7.5' Series

PRESENT FORMAL NAME:

Glamen Wilder House

ORIGINAL FORMAL NAME:

PRESENT USE: House

ORIGINAL USE: Farmhouse

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Deteriorated

THEME:

STYLE: Greek Revival

COUNTY: Rutland

TOWN: Clarendon

LOCATION:

Middle Road, near
North Clarendon

FUNCTIONAL TYPE: Residential

COMMON NAME:

OWNER: Glamen Wilder

ADDRESS: North Clarendon, Vermont

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

DATE BUILT: ca. 1850

GENERAL DESCRIPTION:

Structural System

1. Foundation: Brick Stone Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Balloon Western Platform Post & Beam
 - b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
 - c. Iron
 - d. Steel
 - e. Other:
3. Wall Covering: Clapboard Wood Shingle Board & Batten
Shiplap Novelty Stucco Tile Brick Stone
Slate Sheet Metal Asphalt Shingle Aluminum
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Vault: Brick Stone Concrete
 - c. Other:
5. Roof Covering: Wood Shingle Asphalt Shingle Tile
Slate Sheet Metal Paper Built Up Rolled
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Dormers Bay Windows Ells
Chimneys Cupolas Wings Sheds Other:

Number of Stories: 2½

Approximate Dimensions: 30' x 35' (main block)

Roof Style: Gable Gambrel Flat Shed Hip Mansard

Jerkinhead Monitor Saw Tooth Other:

With Belcast With Parapet With False Front

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Other:

LOCAL ATTITUDES:

Positive Negative Mixed
Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Gable-fronted, three-bay facade. Offset front entrance with pilasters, sidelights and divided transom. Carved work in transom bar and at base of sidelights. Long parlor windows. One-story front porch with fluted columns. Four bays deep, 1½ story north wing. Wood frame ell and sun porch at south are 20th century additions. Corner pilasters, full entablature at cornice, returns. Triangular louvered opening in front gable.


RELATED STRUCTURES:

Deteriorated barn across the road.

STATEMENT OF SIGNIFICANCE:

The front-gabled form, fluted porch columns, perpendicular rear wing, and entrance detailing of this mid-19th century farmhouse are atypical of Greek Revival design in Clarendon. The house was associated with the Marsh family, which had extensive holdings along this stretch of Middle Road in the 19th century. Most of the surrounding farmland was sold off in recent years.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Other:

RECORDED BY:

Kathlyn Hatch

ORGANIZATION:

VT Division for Historic Preservation

DATE RECORDED:

5-76

80-A-58

Vt. Div. for Historic Preservation
Rutland County Clarendon 5/80
Wilder Residence, 1105-19
80-A-58 Gail Byers